



Norifumi Kurakata
NITTAN CO LTD
54-5, 1-CHOME SASAZUKA
SHIBUYA-KU
TOKYO 151-8535 JAPAN

Date: 2016/06/17
Subscriber: 100568097
PartySite:
File No:
Service Request No: 3185900
Project Number: 16SR3185900
PD No: 16022722
PO Number:

Subject: Multiple Listing Correlation Sheet

Dear Norifumi Kurakata,

Enclosed is a copy of your completed Multiple Listing Correlation Sheet covering the Basic File listed below. The following documents were added (new) or revised on 06/17/2016.

<u>Basic File</u>	<u>Vol</u>	<u>ML File</u>	<u>Pages</u>	<u>Revised</u>	<u>New</u>
S35722	1	S35527	ML Cert of Compliance		

Please review this material and report any inaccuracies to UL's Customer Service Professionals. Contact information for all of UL's global offices can be found at <http://ul.com/aboutul/locations>.

If you'd like to receive updated materials FASTER, UL offers electronic access and/or delivery of this material. For more details, contact UL's Customer Service Professionals as shown above, referring to the above Service Request number.

This material is provided on behalf of UL LLC(UL) or any authorized licensee of UL.

NWT File

CERTIFICATE OF COMPLIANCE

Certificate Number 20160617-S35527
Report Reference S35527-20141223
Issue Date 2016-JUNE-17

Issued to: NITTAN CO LTD
54-5, 1-CHOME SASAZUKA
SHIBUYA-KU , TOKYO 151-8535
Japan

This is to certify that representative samples of Audible-signal Appliances ; Signaling Appliances and Equipment for the Hearing Impaired ; Visual-signal Appliances for Fire-protective Signaling Systems
See the addendum page for the Models


Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 464, Standard for Safety for Audible Signal Appliances;
UL 1638, Standard for Safety for Visual Signaling Appliances - Private Mode Emergency and General Utility Signaling ;
UL 1971, Standard for Safety for Signaling Devices for the Hearing Impaired

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20160617-S35527
Report Reference S35527-20141223
Issue Date 2016-JUNE-17

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.


Horns (ULSZ Only) - EVCA-AP-H,

Strobes (UUKC, UVAV Only) - EVCA-AP-S, EVCA-AP-SWP

Horn/strobes (ULSZ, UVAV Only) - EVCA-AP-SH, EVCA-AP-SHWP

Strobes (UUKC Only)

(ULSZ Only) - EVCA-AP-BBX-5



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

