



Norifumi Kurakata
NITTAN CO LTD
54-5, 1-CHOME SASAZUKA
SHIBUYA-KU
TOKYO 151-8535 JAPAN

Date: 2016/06/02
Subscriber: 100568097
PartySite:
File No:
Service Request No: 3185900
Project Number: 16SR3185900
PD No: 16020496
PO Number:

Subject: Multiple Listing Correlation Sheet

Dear Norifumi Kurakata,

Enclosed is a copy of your completed Multiple Listing Correlation Sheet covering the Basic File listed below. The following documents were added (new) or revised on 06/02/2016.

<u>Basic File</u>	<u>Vol</u>	<u>ML File</u>	<u>Pages</u>	<u>Revised</u>	<u>New</u>
S7005	2	S35526	ML Cert of Compliance		
S7005	6	S35526	ML Cert of Compliance		

Please review this material and report any inaccuracies to UL's Customer Service Professionals. Contact information for all of UL's global offices can be found at <http://ul.com/aboutul/locations>.

If you'd like to receive updated materials FASTER, UL offers electronic access and/or delivery of this material. For more details, contact UL's Customer Service Professionals as shown above, referring to the above Service Request number.

This material is provided on behalf of UL LLC (UL) or any authorized licensee of UL.

NWT File

CERTIFICATE OF COMPLIANCE

Certificate Number 20160602-S35526
Report Reference S35526-20140916
Issue Date 2016-JUNE-02

Issued to: NITTAN CO LTD
54-5, 1-CHOME SASAZUKA
SHIBUYA-KU , TOKYO 151-8535
Japan

**This is to certify that
representative samples of** Boxes, Noncoded
Stations for fire alarm service - EVCA-MS-F01
Station adaptor - EVCA-MS-Dkit

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 38 - Manual Signaling Boxes for Fire Alarm Systems
Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20160602-S35526
Report Reference S35526-20140917
Issue Date 2016-JUNE-02

Issued to: NITTAN CO LTD
54-5, 1-CHOME SASAZUKA
SHIBUYA-KU , TOKYO 151-8535
Japan

**This is to certify that
representative samples of** Boxes, Noncoded
Boxes, non-coded - EVCA-MS-S10K,
Accessories: Back Box - EVCA-MS-SBB, EVCA-MS-SWBB

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 38 - Manual Signaling Boxes for Fire Alarm Systems
Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

